

Kenmore 385.18630890, 385.18630 Sewing Service Manual

[DOWNLOAD HERE](#)

Kenmore 385.18630890 385.18630 sewing service manual LOCATE AND IDENTIFY THE PARTS	
..... WHAT TO DO WHEN	
..... THREADING OF MACHINE	
..... 1 2-4 5 SERVICE ACCESS FACE COVER	
..... 6..... IOP COVER	
..... 6..... BASE PLATE	
..... 7..... BED COVER	
..... 7..... BELT COVER	
..... 8..... FREE ARM COVER	
..... 8..... FRONT COVER	
..... 9..... REAR PANEL	
..... 1.0..... MECHANICAL ADJUSTMENT TOP TENSION	
..... 1.1..... PRESSER BAR HEIGHT AND ALIGNMENT	
..... 1.2..... NEEDLE SWING 1.3.....	
STRAIGHT STITCHING 1.4., 1.5..... DISTRIBUTION OF	
NEEDLE SWING 1.6., 1.7..... STRETCH STITCH BALANCE	
..... 1.8., 1.9..... FEED DOG	
HEIGHT..... 2.0., 2.1..... NEEDLE BAR HEIGHT	
..... 2.2., 2.3..... NEEDLE TO SHUTTLE TIMING	
..... 2.4., 2.5..... NEEDLE CLEARANCE TO SHUTTLE	
..... 2.6..... BACKLASH (LOWER SHAFT GEAR)	
..... 2.7..... BUTTONHOLE STITCH BALANCE 2.8., 2.9.....	
NEEDLE POSITION 3.0., 3.1..... ZERO FEEDING	
..... 3.2., 3.3..... BASIC NEEDLE POSITION	
..... 3.4..... BUTTONHOLE FUNCTION	

(I).....3.5..... BUTTONHOLE FUNCTION (2)
.....3.6..... MOTOR BELTTENSION3.7.....
REPLACING THE INDICATOR PLATE3.8..... OILING
.....3.9..... WIRING OF TERMINALBLOCK
.....4.0..... SPECIALTOOLS REQUIRED.....4.1

[DOWNLOAD HERE](#)

Similar manuals: